

Eugene F. Mooney Secretary

## COMMONWEALTH OF KENTUCKY

Site: A.L. Taylor
Process 10, 1)
Dulham M. Carroll
Governor

DEPT. FUND BY TURNER RELIEF TO JUST

ENVIRONMENTAL PROTECTION

GENERAL COUASEL

## DEPARTMENT FOR NATURAL RESOURCES AND ENVIRONMENTAL PROTECTION

BUREAU OF ENVIRONMENTAL PROTECTION

DIVISION OF WATER QUALITY FRANKFORT, KENTUCKY 40601

MEMORANDUM

T0:

Thomas H. Glover

Attorney

Office of General Counsel

FROM:

Clyde P. Baldwin, P.E. With for C. 25

Chief Environmental Engineer Division of Water Quality

DATE:

September 29, 1978

SUBJECT:

A. L. Taylor Drum Cleaning Service

I have received a copy of the hearing officer's report concerning the A. L. Taylor Drum Cleaning Service, and your memo requesting that we prepare suggestions on how the material on-site can be disposed of properly, and in accordance with departmental regulations. Our comments are as follows:

- 1. Incineration appears to be the only safe way of disposing of the material and should be done so by the most expeditious means.
- 2. Should analysis of some of the waste containers demonstrate that some of the material may be disposed of properly by landfilling it may be questionable whether or not that landfilling operation constitute a hazardous materials disposal site and if so, the alternative may be to have it shipped out of state to an approved hazardous materials disposal site.
- 3. Prior to the commencing of any operation for cleanup and removal and proper disposal, a spill prevention control and countermeasure plan should be developed and approved by the Divisions of Water Quality and Hazardous Materials and Waste Management, in order to prevent a problem during such operations and if it were to occur that there is a plan of action to be taken to prevent environmental damage.

Hopefully, with the action now being taken by the department, after some two years of being in limbo, this will bring about the resolution of one of Kentucky's worst and possibly one of the most potentially dangerous situations within the state.

CPB:1cc



000069